

Garrison Engineer  
868 Engr Wks Sec  
PIN 913 868  
c/o 99 APO

2000/APS/ 11 /E2

16 Jul 2019

KV, Dimapur  
Project Sewak  
c/o 99 APO  
Nagaland

**BUILDING SAFETY CERTIFICATE**

1. Ref your letter No 1865380/2019-20/KVD/3124 dt 14 May 2019.
2. Building safety cert as asked vide your letter under ref is fwd herewith as per Appx att.



(Ravindra Kumar)  
Maj  
Garrison Engineer

Encls : (As above)

Copy to :-

AGE B/R-II - for info wrt your letter No 204/KV/E2 dt 06 Jul 2019.

## BUILDING SAFETY CERTIFICATE

"It is certified that the visual inspections of the buildings occupied by Kendriya Vidyalaya, Dimapur, C/o HQ 3 Corps, 939 FPO have been inspected by the representative of GE 868 EWS and as on date the buildings are found safe for occupation". However, it is observed that the maint of the bldgs has not been carried out to upgrade the life of bldgs and also to address the unseen defects as the bldg is located in seismic Zone-V and non adherence to periodical maint may lead to some minor incidents.

Station : C/o 99 APO

Dated : *16* Jul 2019



(Ravindra Kumar)  
Maj  
Garrison Engineer